

SUZUKI et al Q62980 February 7, 2001 Darryl Mexic 202-293-7060 1 of 16

FIG.1









FIG.3






FIG.5

February 7, 2001 Darryl Mexic 202-293-7060 4 of 16




FIG.6A





FIG.6B






FIG.8

FIG.9

202-293-7060







FIG. 10









iái


LENS DRIVE DEVICE, SUSPENSION UNIT.....
SUZUKI et al Q62980
February 7, 2001
Darryl Mexic
202-293-7060
8 of 16

PU01-00110 -EP01-00110-


## FIG. 13








Darryl Mexic 202-293-7060 10 of 16








FIG. 18

The little of th

LENS DRIVE DEVICE, SUSPENSION UNIT.....
SUZUKI et al Q62980
February 7, 2001
Darryl Mexic
202-293-7060 13 of 16

FIG. 19




FIG. 20

37

30

Fig. 20

Fig. 20

To Ti




FIG.21




FIG. 22

LENS DRIVE DEVICE, SUSPENSION UNIT.....
SUZUKI et al Q62980
February 7, 2001
Darryl Mexic
202-293-7060
15 of 16


FIG. 23 525 51 52a 58 Gt -Gp Gf


53

59

Sand the first two to the first two to the first two

The state of the s





Hard Hard Hard Hard Hard Hard Hard

FIG. 25




FIG. 26